


## Set Defaults Bar Code



RETURN TO FACTORY DEFAULTS

## Enter Key Bar Code (Carriage Return/Line Feed)

Add an Enter key after scanned data.



ADD AN ENTER KEY (CARRIAGE RETURN/LINE FEED)

## Tab Key Bar Code

Add a Tab key after scanned data.



ADD A TAB KEY

## USB Caps Lock Override



USB - OVERRIDE CAPS LOCK KEY (ENABLE)



\*USB - DO NOT OVERRIDE CAPS LOCK KEY (DISABLE)